



Wyr=0,53
Frez=0,00

P-30 0+725,00



W=0,14
N=0,00
Wyr=0,32
Frez=0,00

P-31 0+750,00



P-32 0+772,00

